

INSPECTION REPORT


End of contract

GENERAL INFO

File	306917
License plate	1YGW993
Vehicle identification number	W1K1771031J256756
Dossier	2020 057 185
Make	Mercedes A Berline 180 d Bus.S
Mileage	154625
First registration	27/08/2020
client availability date	04/03/2026
inspectionDate	07/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
84	Door Front Left // Repair & Painting	N
93	Rocker Panel Left // Repair & Painting	Y
161	Roof // Smart Repair Medium	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Damage within Renta-norm-scratch



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Left // Repair & Painting-dent



Roof // Smart Repair Medium-dent



Door Front Left // Repair & Painting-dent



Bumper Front // Painting-stone chipping



Wheel Two Tone Rear Right // Repair-scratch