

INSPECTION REPORT



End of contract

GENERAL INFO

File	300450
License plate	2BSH107
Vehicle identification number	W1N1671171A662444
Dossier	1000191935
Make	Mercedes GLE 350 de 4M
Mileage	159302
First registration	07/03/2022
client availability date	09/12/2025
inspectionDate	12/12/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
135	Bumper Rear // Replace & Painting	N
174	Light / Rear Right / Replace	N
320	Wheel Two Tone Rear Left // Repair	N
326	Tyre Rear Left // Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
111	Wing Rear Left // Smart Repair Medium	N
413	Seat Front Left / Rear Coating / Replace	N
883	Key Price Range 2 //	N

Damage Pictures



Damage within Renta-norm-scratch



Seat Front Left / Rear Coating / Replace-hole




Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Medium-scratch + dent



Light / Rear Right / Replace-scratch



Bumper Rear // Replace & Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Tyre Rear Left // Replace-tear