

INSPECTION REPORT

End of contract

GENERAL INFO

File	317748
License plate	2AEW726
Vehicle identification number	VF3LCYHZKMS046593
Dossier	2020346090
Make	Peugeot 308 SW 1.5BHDi 130 Ac.
Mileage	137668
First registration	12/03/2021
client availability date	10/07/2026
inspectionDate	05/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
634	Rear Left Door Interior Coating // Replace Completely	N
637	Rear Left Door Interior Coating / Grid Loudspeaker / Replace	N
801	See External Expertise	N
891	Lettering Removal 15min	N
14	Bumper Front // Repair & Painting	N
41	Windshield // Replace	N
83	Door Front Left // Painting	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	N
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
184	Wing Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
316	Tyre Front Left // Replace	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
565	Dashboard / Storage Tray / Replace	N
568	Dashboard / Ventilation Outlet / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
611	Front Left Door Interior Coating // Repair	N
621	Front Right Door Interior Coating // Repair	N
621	Front Right Door Interior Coating // Repair	Y
644	Rear Right Door Interior Coating // Replace Completely	N

773	Interior / A Pillar Lower Cover / Replace	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Light / Rear left / Replace-scratch





Wheel Alloy Rear Left // Repair-scratch



Door Front Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Polish-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch




Front Left Door Interior Coating // Repair-scratch



Interior // Repair 1-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Dashboard / Storage Tray / Replace-scratch



Front Right Door Interior Coating // Repair-scratch



Front Right Door Interior Coating // Repair-worn



Rocker Panel Right // Smart Repair Medium-dent








Bumper Front // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent






Wing Rear Left // Repair & Painting-scratch + dent




Windshield // Replace-cracked



Dashboard / Ventilation Outlet / Replace-cracked



Tyre Front Left // Replace-tear



Interior Cleaning // Small-stain



Seat Front Left / Bottom Coating / Replace-worn




Rear Left Door Interior Coating / Grid Loudspeaker / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Lettering Removal 15min-



See External Expertise-