

INSPECTION REPORT



End of contract

GENERAL INFO

File	306405
License plate	1YWA274
Vehicle identification number	TMBJF7NU7M5023839
Dossier	2020190067
Make	Skoda Karoq 1.6TDi 85kW Ambiti
Mileage	119601
First registration	07/01/2021
client availability date	13/03/2026
inspectionDate	18/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
538	Trunk Compartment / Boot Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures





Damage within Renta-norm-



Bumper Rear // Polish-scratch



Door Rear Left // Painting-scratch



Wing Front Left // Polish-scratch



Interior / Side Cover rear Seat / Replace-scratch



Wing Rear Left // Polish-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch





Rear Right Door Interior Coating // Replace Completely-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-missing



Trunk Compartment / Boot Cover / Replace-missing



Front Bonnet // Polish-Chemical reaction



See External Expertise-Splashes