

INSPECTION REPORT

End of contract

GENERAL INFO

File	312887
License plate	2APD441
Vehicle identification number	WDD2050001R561793
Dossier	2021 132 097
Make	Mercedes C 180 d 90kW Aut.Bus.
Mileage	189104
First registration	01/06/2021
client availability date	19/05/2026
inspectionDate	11/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
133	Bumper Rear // Painting	Y
186	Wing Rear Right // Polish	Y
230	Wing Front right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Front Bonnet // Painting-stone chipping



Wing Front right // Smart Repair Small-stone chipping