

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	309040
License plate	2BUG314
Vehicle identification number	W1K1183121N294134
Dossier	2021146280
Make	Mercedes CLA 200 d Bus.Sol.Aut
Mileage	101204
First registration	24/03/2022
client availability date	27/03/2026
inspectionDate	02/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	Y
41	Windshield // Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
544	Interior / Floor Covering / Replace	Y
772	Interior / A Pillar Upper Cover / Replace	Y

## Damage Pictures




Rocker Panel Left // Smart Repair Medium-dent



Bumper Front // Painting-bad repair



Windshield // Replace-glass damage



Interior / A Pillar Upper Cover / Replace-tear




Interior / Floor Covering / Replace-worn



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch