

INSPECTION REPORT

End of contract


GENERAL INFO

File	317158
License plate	UX7424
Vehicle identification number	TMBLN9NS3N8054303
Dossier	2022033010
Make	Skoda Kodiaq TDI200 4x4 Style
Mileage	167515
First registration	07/06/2022
client availability date	02/07/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
194	Door Rear Right // Repair & Painting	Y
210	Door Front Right // Smart Repair Small	Y
217	Door Front Right / Trim / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Front Bonnet // Painting-scratch



Roof // Polish-scratch



Bumper Rear // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Right // Repair & Painting-dent



Roof // Smart Repair Medium-dent



Door Front Right / Trim / Replace-scratch + dent



Interior // Repair 1-worn