

INSPECTION REPORT



End of contract

GENERAL INFO

File	318210
License plate	2AVY810
Vehicle identification number	W1V44770513907710
Dossier	2021 042 056
Make	Mercedes Vito Combi 114CDI Pro
Mileage	69391
First registration	10/08/2021
client availability date	25/08/2026
inspectionDate	31/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	4	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
33	Front Bonnet // Repair & Painting	Y
84	Door Front Left // Repair & Painting	Y
113	Wing Rear Left // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
221	Side View Mirror Right // Plastic Repair	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
316	Tyre Front Left // Replace	Y
346	Tyre Front Right // Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y


Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left // Painting-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Door Front Right // Smart Repair Small-dent




Front Left Door Interior Coating // Replace Completely-dent



Door Front Left // Repair & Painting-dent



Front Right Door Interior Coating // Replace Completely-dent



Front Bonnet // Repair & Painting-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Tyre Front Right // Replace-worn



Tyre Front Left // Replace-worn