

INSPECTION REPORT


End of contract


GENERAL INFO

File	309818
License plate	2ATA822
Vehicle identification number	YV1LFK2VCM1767637
Dossier	2021 041 175
Make	Volvo XC90 B5 D Mom.Pro 4WD GT
Mileage	204638
First registration	06/07/2021
client availability date	02/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
533	Trunk Compartment / Side Cover Right / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
16	Bumper Front // Polish	Y
237	Wing Front right / Trim / Replace	Y
161	Roof // Smart Repair Medium	N
197	Door Rear Right / Trim / Replace	N
18	Bumper Front / Spoiler / Replace	N
66	Wing Front Left // Polish	Y
67	Wing Front Left / Trim / Replace	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
107	Door Rear Left / Trim / Replace	Y
116	Wing Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	Y
134	Bumper Rear // Repair & Painting	N
156	Rear Bonnet // Polish	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
282	Bumper Rear / Trim Center / Replace	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

411	Seat Front Left // Repair	N
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
614	Front Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N

Damage Pictures



Door Rear Right // Painting-bad repair



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Seat Front Left // Repair-scratch



Seat Rear Left // Repair-scratch



Front Left Door Interior Coating // Replace Completely-scratch




Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent





Bumper Rear // Repair & Painting-scratch + dent



Bumper Rear / Trim Center / Replace-scratch



Rear Bonnet // Polish-scratch



Light / Rear left / Replace-scratch





Rear Bonnet / Rear Window / Replace-scratch





Light / Rear Right / Replace-scratch



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Bumper Front / Spoiler / Replace-scratch



Wing Front Left / Trim / Replace-scratch



Wing Front Left // Polish-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left / Trim / Replace-scratch



Door Rear Left // Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Polish-scratch



Door Rear Right / Trim / Replace-scratch



Roof // Smart Repair Medium-scratch + dent