

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	308728
License plate	1YPT162
Vehicle identification number	TMBJG7NU9M2018060
Dossier	2020234003
Make	Skoda Karoq 1.6TDi 85kW Ambiti
Mileage	107412
First registration	29/10/2020
client availability date	20/03/2026
inspectionDate	25/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
186	Wing Rear Right // Polish	N
196	Door Rear Right // Polish	N
214	Door Front Right // Repair & Painting	N
236	Wing Front right // Polish	N
41	Windshield // Replace	N
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
154	Rear Bonnet // Repair & Painting	N
634	Rear Left Door Interior Coating // Replace Completely	Y
883	Key Price Range 2 //	N


## Damage Pictures



Damage within Renta-norm-scratch



Windshield // Replace-glass damage



Key Price Range 2 //-missing



Door Rear Left // Painting-scratch




Door Front Left // Painting-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Wing Front right // Polish-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Polish-scratch



Door Front Right // Repair & Painting-scratch + dent