

INSPECTION REPORT


End of contract

GENERAL INFO

File	309260
License plate	2ABC872
Vehicle identification number	W1K2052011G078399
Dossier	2020252020
Make	Mercedes C Br.200 d 118kW Bus.
Mileage	70321
First registration	05/02/2021
client availability date	27/03/2026
inspectionDate	03/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
165	Roof // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
883	Key Price Range 2 //	N

Damage Pictures




Wheel Alloy Rear Right // Repair-



Wing Rear Left // Polish-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent



Bumper Front // Painting-bad repair



Roof // Polish-Chemical reaction