

INSPECTION REPORT


End of contract

GENERAL INFO

File	306385
License plate	1YNN963
Vehicle identification number	VR3UDYHZRLJ820179
Dossier	2020 084 046
Make	Peugeot 2008 1.5BlueHDi 96kW A
Mileage	132330
First registration	13/10/2020
client availability date	04/03/2026
inspectionDate	10/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
50	Headlight / Front left / Repair	N
72	Side View Mirror Left // Painting	Y
109	Door Rear Left / Window / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	N
175	Light / Rear Right On Rear Bonnet / Replace	N
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
211	Door Front Right // Smart Repair Medium	Y
282	Bumper Rear / Trim Center / Replace	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-scratch



Roof // Smart Repair Medium-dent



Door Rear Right // Smart Repair Medium-dent



Door Front Right // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Polish-scratch





Light / Rear Right On Rear Bonnet / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Door Rear Left / Window / Replace-scratch



Side View Mirror Left // Painting-scratch



Headlight / Front left / Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch