

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306433
License plate	1XKG560
Vehicle identification number	TMBJP7NE7K0117803
Dossier	2020 009 029
Make	Skoda Oct.Com.1.0TSI 85kW Ambi
Mileage	131370
First registration	14/02/2019
client availability date	20/02/2026
inspectionDate	04/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages

Type

Acceptable

### Damage Pictures



Damage within Renta-norm-scratch