

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306122
License plate	2BJT356
Vehicle identification number	YV1XZL4V1N2710355
Dossier	2021 173 089
Make	Volvo XC40 T2 Momentum Core
Mileage	97869
First registration	10/12/2021
client availability date	24/02/2026
inspectionDate	04/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
154	Rear Bonnet // Repair & Painting	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
411	Seat Front Left // Repair	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	N
543	Interior // Ionization Odor	N
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures





Damage within Renta-norm-





Wheel Alloy Rear Left // Repair-scratch



Seat Front Left // Repair-scratch



Seat Front Left // Repair-Incinerated



Rear Bonnet // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-cracked



Interior Cleaning // Small-stain



Wheel Alloy Rear Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Seat Front Right // Repair-scratch





Bumper Rear // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Side View Mirror Left // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch