

# INSPECTION REPORT




End of contract

## GENERAL INFO

File	307703
License plate	1YMT988
Vehicle identification number	TMBJJ7NX9MY050984
Dossier	2020 188 028
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	118335
First registration	22/10/2020
client availability date	13/03/2026
inspectionDate	23/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
60	Wing Front Left // Smart Repair Small	N
159	Rear Bonnet / Rear Window / Replace	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

## Damage Pictures



Damage within Renta-norm-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Front Left // Smart Repair Small-dent



Bumper Front // Replace & Painting-cracked



Rear Bonnet / Rear Window / Replace-scratch