

INSPECTION REPORT

End of contract

GENERAL INFO

File	306438
License plate	1YVP649
Vehicle identification number	YV1XZ72VDM2450202
Dossier	1000 191 610
Make	Volvo XC40 D3 Momentum Pro Gtr
Mileage	271080
First registration	04/01/2021
client availability date	24/02/2026
inspectionDate	11/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
210	Door Front Right // Smart Repair Small	N
214	Door Front Right // Repair & Painting	N
234	Wing Front right // Repair & Painting	N
237	Wing Front right / Trim / Replace	N
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
18	Bumper Front / Spoiler / Replace	N
31	Front Bonnet // Smart Repair Small	N
67	Wing Front Left / Trim / Replace	N
84	Door Front Left // Repair & Painting	N
106	Door Rear Left // Polish	Y
151	Rear Bonnet // Smart Repair Medium	N
154	Rear Bonnet // Repair & Painting	N
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Damage within Renta-norm-



Dashboard / Steering Wheel / Replace-worn



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Light / Rear Right / Replace-scratch



Seat Front Right // Repair-scratch




Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Rear Right Door Interior Coating // Repair-scratch



Rear Bonnet // Smart Repair Medium-scratch



Interior / Side Cover rear Seat / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Front Bonnet // Smart Repair Small-scratch + dent



Seat Front Left // Repair-scratch



Rear Left Door Interior Coating // Repair-scratch



Roof // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch




Door Front Right // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Door Front Right // Smart Repair Small-scratch



Bumper Rear // Smart Repair Large-scratch



Bumper Rear / Lower Cover Not Painted / Replace-cracked