

INSPECTION REPORT


End of contract

GENERAL INFO

File	314113
License plate	2CCT871
Vehicle identification number	VSSZZZKJZNR105151
Dossier	2022045018
Make	Seat Arona 1.0 81kW Move DSG
Mileage	117389
First registration	08/06/2022
client availability date	08/06/2026
inspectionDate	11/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Small-dent



Windshield // Repair-glass damage