

INSPECTION REPORT

End of contract

GENERAL INFO

File	322094
License plate	1YGA864
Vehicle identification number	VXKUPMHDL4320776
Dossier	2020 051 114
Make	Opel Corsa 1.2 75 Edition 5d/p
Mileage	66607
First registration	20/08/2020
client availability date	21/09/2026
inspectionDate	24/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
33	Front Bonnet // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	Y
153	Rear Bonnet // Painting	Y
163	Roof // Repair & Painting	Y
183	Wing Rear Right // Painting	N
213	Door Front Right // Painting	Y

Damage Pictures



Rear Bonnet // Painting-scratch



Door Front Right // Painting-scratch





Roof // Repair & Painting-dent



Bumper Front // Smart Repair Large-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Painting-bad repair



Front Bonnet // Repair & Painting-bad repair