

INSPECTION REPORT

End of contract

GENERAL INFO

File	321093
License plate	PW4003
Vehicle identification number	YV1PW68UCL1141016
Dossier	2020 041 033
Make	Volvo V90 D5 235 AWD Momen.Pro
Mileage	182142
First registration	24/06/2020
client availability date	28/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
16	Bumper Front // Polish	Y
40	Windshield // Repair	Y
64	Wing Front Left // Repair & Painting	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
191	Door Rear Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	N
234	Wing Front right // Repair & Painting	N
411	Seat Front Left // Repair	Y
421	Seat Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right / Replace-scratch



Bumper Front // Polish-scratch



Door Front Left // Painting-scratch



Door Rear Left // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-dent




Seat Front Left // Repair-dent




Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Door Front Right // Smart Repair Small-dent



Wing Front right // Repair & Painting-dent




Door Rear Right // Smart Repair Medium-scratch + dent




Wing Front Left // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Rear // Painting-bad repair



Windshield // Repair-glass damage



Lettering Removal 15min-