

INSPECTION REPORT


End of contract

GENERAL INFO

File	313693
License plate	1XGU637
Vehicle identification number	SB1Z93BEX0E083273
Dossier	2019289157
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	157347
First registration	02/01/2020
client availability date	26/05/2026
inspectionDate	04/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Rocker Panel Left // Smart Repair Medium-scratch




Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch




Door Front Left // Smart Repair Small-scratch




Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch

