

INSPECTION REPORT


End of contract

GENERAL INFO

File	306981
License plate	2AWX930
Vehicle identification number	KMHC851CGLU216583
Dossier	2021 161 073
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	136652
First registration	23/08/2021
client availability date	27/02/2026
inspectionDate	10/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
54	Headlight / Front left / Replace	N
32	Front Bonnet // Painting	N
64	Wing Front Left // Repair & Painting	Y
84	Door Front Left // Repair & Painting	N
88	Door Front Left / Door Handle / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	N
163	Roof // Repair & Painting	N
165	Roof // Polish	Y
169	Rear Bonnet / Spoiler / Replace & Painting	N
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	N
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
225	Side View Mirror Right // Polish	Y
236	Wing Front right // Polish	Y
258	Towing Cover Rear // Replace	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	N
453	Seat Rear Right / Rear Coating / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	Y

538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	Y
544	Interior / Floor Covering / Replace	N
556	Central Console / Cover Armrest / Replace Cover Armrest	N
561	Dashboard // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
611	Front Left Door Interior Coating // Repair	N
624	Front Right Door Interior Coating // Replace Completely	N
631	Rear Left Door Interior Coating // Repair	N
638	Rear Left Door Interior Coating / Door Handle / Replace	N
641	Rear Right Door Interior Coating // Repair	N
773	Interior / A Pillar Lower Cover / Replace	Y
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Damage within Renta-norm-scratch



Towing Cover Rear // Replace-cracked



Door Front Left / Door Handle / Replace-missing



Trunk Compartment / Boot Cover / Replace-missing



Central Console / Cover Armrest / Replace Cover
Armrest-tear



Door Rear Right / Trim / Replace-tear



Front Right Door Interior Coating // Replace Completely-
tear



Interior Cleaning // Small-stain



Interior // Repair 1-Remainder stickers




Interior / Floor Covering / Replace-hole



Seat Rear Right / Rear Coating / Replace-hole



Bumper Rear // Painting-scratch





Rear Bonnet / Spoiler / Replace & Painting-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Door Rear Right // Polish-scratch



Roof // Polish-scratch



Side View Mirror Right // Polish-scratch



Wing Front right // Polish-scratch




Wheel Alloy Front Right // Repair-scratch



Door Rear Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch




Rear Right Door Interior Coating // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Dashboard // Repair-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Seat Front Left // Repair-scratch



Rear Left Door Interior Coating / Door Handle / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch




Front Left Door Interior Coating // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch





Rocker Panel Right // Smart Repair Medium-scratch + dent




Wing Rear Left // Repair & Painting-scratch + dent



Front Bonnet // Painting-scratch + dent




Wing Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Roof // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Front Right // Painting-bad repair



Light / Rear Right / Replace-cracked



Headlight / Front left / Replace-scratch



Bumper Front // Replace & Painting-cracked