

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	310274
License plate	2BGX086
Vehicle identification number	W1K1771101J329415
Dossier	2021 022 025
Make	Mercedes A Berline 180 d Busin
Mileage	75949
First registration	23/11/2021
client availability date	16/04/2026
inspectionDate	04/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





## DAMAGES

Damages	Type	Acceptable
12 Bumper Front // Smart Repair Large		N
228 Side View Mirror Right / Direction Indicator / Replace		N
320 Wheel Two Tone Rear Left // Repair		Y

## Damage Pictures




Damage within Renta-norm-



Bumper Front // Smart Repair Large-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Two Tone Rear Left // Repair-Chemical reaction