

INSPECTION REPORT

End of contract

GENERAL INFO

File	315409
License plate	2BSH914
Vehicle identification number	VF3MCYHZUMS260682
Dossier	2021 258 048
Make	Peugeot 5008 1.5BHDi 96kW Allu
Mileage	119236
First registration	07/03/2022
client availability date	15/06/2026
inspectionDate	22/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
138	Bumper Rear / Lower Cover Not Painted / Replace	N
148	Back Side / Reflector R / Replace	N
41	Windshield // Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	N
135	Bumper Rear // Replace & Painting	N
181	Wing Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
225	Side View Mirror Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
413	Seat Front Left / Rear Coating / Replace	Y

Damage Pictures



Windshield // Replace-glass damage



Door Front Right // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Smart Repair Small-scratch + dent



Wing Rear Right // Smart Repair Medium-scratch + dent



Bumper Rear // Replace & Painting-cracked




Side View Mirror Right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Seat Front Left / Rear Coating / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Back Side / Reflector R / Replace-cracked