

INSPECTION REPORT




End of contract

GENERAL INFO

File	313697
License plate	2BRP665
Vehicle identification number	SB1Z93BE00E284325
Dossier	2022 039 046
Make	Toyota Corolla TS 1.8 Hybrid D
Mileage	166577
First registration	25/02/2022
client availability date	27/05/2026
inspectionDate	06/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
213	Door Front Right // Painting	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Door Front Left // Smart Repair Small-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent



Door Front Right // Painting-scratch + dent



Interior // Repair 1-Incinerated