

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	308753
License plate	2BSQ778
Vehicle identification number	W1K1186101N270649
Dossier	2022 049 042
Make	Mercedes CLA SB 180 d Bus.Sol.
Mileage	143509
First registration	09/03/2022
client availability date	23/03/2026
inspectionDate	02/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
227	Side View Mirror Right / Shell / Replace Not Painted	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
18	Bumper Front / Spoiler / Replace	Y
31	Front Bonnet // Smart Repair Small	Y
41	Windshield // Replace	Y
83	Door Front Left // Painting	Y
106	Door Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
165	Roof // Polish	Y
222	Side View Mirror Right // Painting	Y
271	Bumper Front / Trim Left / Replace	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
774	Interior / Side Cover rear Seat / Replace	Y

## Damage Pictures



Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Door Front Left // Painting-scratch




Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Front Bonnet // Smart Repair Small-dent



Bumper Front / Trim Right / Replace-scratch + dent



Windshield // Replace-glass damage




Roof // Polish-scratch




Light / Rear left / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch