

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	281979
License plate	2AHR480
Vehicle identification number	WBA71AB0105T61106
Dossier	2020 342 044
Make	BMW X1 xDrive 25e 162kW Aut
Mileage	146582.00
First registration	07/04/2021
	21/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
187	Wing Rear Right / Trim / Replace	Y
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
411	Seat Front Left // Repair	Y
860	Interior Cleaning // Small	N

Damage Pictures



Front Bonnet // Polish-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Polish-scratch



Door Rear Right // Polish-scratch



Wing Rear Right / Trim / Replace-scratch



Rear Bonnet // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Seat Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch



Interior Cleaning // Small-stain