

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	279926
License plate	2ANB560
Vehicle identification number	WVGZZA1ZMV156442
Dossier	2021 036 151
Make	Volkswagen T-Roc 1.0TSI 81kW U
Mileage	73733.00
First registration	20/05/2021
	02/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
197	Door Rear Right / Trim / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch







Bumper Rear // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Interior Cleaning // Small-stain



Door Rear Right / Trim / Replace-bad position