

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307930
License plate	2AEB427
Vehicle identification number	W1K1771861J302781
Dossier	2020 146 108
Make	Mercedes A Berline 250e PHEV B
Mileage	109429
First registration	05/03/2021
client availability date	12/03/2026
inspectionDate	18/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
139	Bumper Rear / Spoiler / Replace	N
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
81	Door Front Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y


## Damage Pictures




Damage within Renta-norm-scratch




Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Door Rear Left // Painting-scratch + dent



Bumper Rear // Painting-scratch



Bumper Rear / Spoiler / Replace-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch