

INSPECTION REPORT




End of contract

GENERAL INFO

File	321261
License plate	1WXE527
Vehicle identification number	WDD1771031J150763
Dossier	2019276200
Make	Mercedes A Berline 180 d Bus.S
Mileage	161838
First registration	14/10/2019
client availability date	02/09/2026
inspectionDate	11/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
54	Headlight / Front left / Replace	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
183	Wing Rear Right // Painting	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
233	Wing Front right // Painting	Y
341	Wheel Alloy Front Right // Repair	Y

Damage Pictures



Bumper Rear // Polish-scratch



Wing Rear Left // Polish-scratch





Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Headlight / Front left / Replace-scratch



Front Bonnet // Painting-scratch




Bumper Front // Painting-scratch



Wing Front right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Door Rear Right // Polish-scratch



Wing Rear Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent