

INSPECTION REPORT


End of contract

GENERAL INFO

File	319804
License plate	2ARM520
Vehicle identification number	TMBJJ7NS0M8521103
Dossier	2021 025 142
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	110453
First registration	22/06/2021
client availability date	07/08/2026
inspectionDate	26/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
186	Wing Rear Right // Polish	Y
190	Door Rear Right // Smart Repair Small	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
116	Wing Rear Left // Polish	Y
154	Rear Bonnet // Repair & Painting	N
205	Rocker Panel Right // Polish	Y
213	Door Front Right // Painting	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wing Rear Left // Polish-scratch




Rocker Panel Left // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Door Rear Left // Repair & Painting-scratch + dent




Rear Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Door Front Right // Painting-scratch



Rocker Panel Right // Polish-scratch



Door Rear Right // Smart Repair Small-scratch



Wing Rear Right // Polish-scratch