

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	302188
License plate	2BPN235
Vehicle identification number	W1K1183861N282613
Dossier	2021208125
Make	Mercedes CLA 250 e Bus.Solut.A
Mileage	44409
First registration	04/02/2022
client availability date	13/02/2026
inspectionDate	03/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
18	Bumper Front / Spoiler / Replace	N
891	Lettering Removal 15min	N

## Damage Pictures



Damage within Renta-norm-



Bumper Front // Replace & Painting-cracked



Bumper Front / Spoiler / Replace-cracked



Lettering Removal 15min-Remainder stickers