

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	309068
License plate	2FKC681
Vehicle identification number	SJNFAAF16U1285783
Dossier	2023354006
Make	Nissan Juke 1.0 84kW N-Design
Mileage	10131
First registration	29/05/2024
client availability date	26/03/2026
inspectionDate	27/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
183	Wing Rear Right // Painting	Y
222	Side View Mirror Right // Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
881	Key Price Range 1 //	N

## Damage Pictures



Side View Mirror Right // Painting-scratch



Wing Rear Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch