

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307333
License plate	2DRS362
Vehicle identification number	VR3FRHNSLPY558476
Dossier	2022 188 215
Make	Peugeot 308 SW 1.2 130 Active
Mileage	32806
First registration	06/06/2023
client availability date	04/03/2026
inspectionDate	12/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
41	Windshield // Replace	Y
84	Door Front Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
181	Wing Rear Right // Smart Repair Medium	Y
202	Rocker Panel Right // Painting	Y
203	Rocker Panel Right // Repair & Painting	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

## Damage Pictures





Damage within Renta-norm-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Rocker Panel Right // Repair & Painting-dent



Roof // Smart Repair Medium-dent



Bumper Rear // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Medium-scratch + dent






Rocker Panel Right // Painting-bad repair



Interior Cleaning // Small-stain



Windshield // Replace-scratch