

INSPECTION REPORT


End of contract

GENERAL INFO

File	310038
License plate	2CLC416
Vehicle identification number	W1K1771101J368560
Dossier	2021099047
Make	Mercedes A Berline 180 d Busin
Mileage	43020
First registration	01/09/2022
client availability date	08/04/2026
inspectionDate	15/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
12	Bumper Front // Smart Repair Large	N
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
165	Roof // Polish	Y
233	Wing Front right // Painting	Y


Damage Pictures



Roof // Polish-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front right // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch