

INSPECTION REPORT


End of contract


GENERAL INFO

File	315237
License plate	JV5908
Vehicle identification number	VR3USHNSSNJ662317
Dossier	2021342102
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	64538
First registration	28/07/2022
client availability date	12/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
33	Front Bonnet // Repair & Painting	N
38	Front Bonnet / Insulation / Replace	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	Y
282	Bumper Rear / Trim Center / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Rear / Trim Center / Replace-scratch



Door Front Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch




Rocker Panel Right // Smart Repair Medium-scratch



Front Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-dirty



Front Bonnet / Insulation / Replace-tear