

INSPECTION REPORT



End of contract

GENERAL INFO

File	305272
License plate	2AFV898
Vehicle identification number	TMBJH7NP1M7060121
Dossier	2020 140 043
Make	Skoda Sup.Comb.TDi 150 Style D
Mileage	87034
First registration	22/03/2021
client availability date	02/03/2026
inspectionDate	07/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES



Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	Y
72	Side View Mirror Left // Painting	N
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
133	Bumper Rear // Painting	Y
153	Rear Bonnet // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
538	Trunk Compartment / Boot Cover / Replace	N
625	Front Right Door Interior Coating / Reflector / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Painting-scratch




Bumper Rear // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wing Rear Right // Polish-scratch



Bumper Front // Repair & Painting-scratch + dent



Front Right Door Interior Coating / Reflector / Replace-missing



Trunk Compartment / Boot Cover / Replace-missing



Interior Cleaning // Small-stain