

INSPECTION REPORT



End of contract


GENERAL INFO

File	321192
License plate	VZ4241
Vehicle identification number	VF3MCYHZUNS037513
Dossier	2021245002
Make	Peugeot 3008 BlueHDi 130 Activ
Mileage	122566
First registration	09/03/2022
client availability date	31/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
136	Bumper Rear // Polish	Y
186	Wing Rear Right // Polish	Y
191	Door Rear Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
237	Wing Front right / Trim / Replace	N
311	Wheel Alloy Front Left // Repair	Y
431	Seat Rear Left // Repair	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Seat Rear Left // Repair-scratch




Door Front Left // Smart Repair Medium-scratch




Wheel Alloy Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Polish-scratch




Door Front Right // Painting-scratch



Door Rear Right // Smart Repair Medium-scratch



Wing Rear Right // Polish-scratch



Rocker Panel Left // Smart Repair Medium-dent



Interior // Repair 1-Incinerated



Wing Front right / Trim / Replace-Chemical reaction