

INSPECTION REPORT


End of contract

GENERAL INFO

File	318677
License plate	2CKG436
Vehicle identification number	W1K5J8GB9PN335866
Dossier	2022 125 019
Make	Mercedes CLA 250 e AMG Line Au
Mileage	51035
First registration	23/08/2022
client availability date	31/07/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages		Type	Acceptable
32	Front Bonnet // Painting		Y
91	Rocker Panel Left // Smart Repair Medium		Y
106	Door Rear Left // Polish		Y
153	Rear Bonnet // Painting		Y
165	Roof // Polish		Y
310	Wheel Two Tone Front Left // Repair		N
320	Wheel Two Tone Rear Left // Repair		N
330	Wheel Two Tone Rear Right // Repair		N
340	Wheel Two Tone Front Right // Repair		N
540	Interior // Repair 1		N
860	Interior Cleaning // Small		Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent




Front Bonnet // Painting-bad repair






Door Rear Left // Polish-bad repair



Interior // Repair 1-Incinerated



Rear Bonnet // Painting-Chemical reaction



Roof // Polish-Chemical reaction



Interior Cleaning // Small-stain