

INSPECTION REPORT

End of contract

GENERAL INFO

File	312840
License plate	2BGZ366
Vehicle identification number	VF3MRHNSUMS227687
Dossier	2021103019
Make	Peugeot 3008 1.2PTech 96kW GT
Mileage	57685
First registration	23/11/2021
client availability date	15/05/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
12	Bumper Front // Smart Repair Large	N
67	Wing Front Left / Trim / Replace	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
80	Door Front Left // Smart Repair Small	N
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
174	Light / Rear Right / Replace	Y
205	Rocker Panel Right // Polish	Y
213	Door Front Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures



Door Front Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Rocker Panel Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Painting-scratch



Rear Bonnet // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front Left / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch