

INSPECTION REPORT

End of contract

GENERAL INFO

File	310943
License plate	2BRQ718
Vehicle identification number	W1K2052131G092233
Dossier	2021 340 003
Make	Mercedes C Break 300 de Bus.So
Mileage	184243
First registration	25/02/2022
client availability date	24/04/2026
inspectionDate	07/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y

Damage Pictures



Damage within Renta-norm-



Bumper Front // Smart Repair Large-scratch