

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	307059
License plate	2ACX991
Vehicle identification number	VSSZZZKLZMR035426
Dossier	2020 274 028
Make	Seat Leon ST 1.0TSI 90 Move!
Mileage	148454
First registration	24/02/2021
client availability date	06/03/2026
inspectionDate	16/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES


Damages	Type	Acceptable
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
210	Door Front Right // Smart Repair Small	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	Y
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	Y

## Damage Pictures





Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch




Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch




Wheel Alloy Front Left // Repair-scratch



Door Front Right // Smart Repair Small-dent



Bumper Rear // Painting-scratch + dent



Interior // Repair 1-Incinerated



Interior Cleaning // Small-stain



Interior // Ionization Odor-bad smell



Key Price Range 2 //-N comf / out of order