



ARVAL
BNP PARIBAS GROUP

PK4537

INSPECTION REPORT

End of contract

GENERAL INFO

File	321191
License plate	PK4537
Vehicle identification number	W1KEG1BB5SF062571
Dossier	2024079049
Make	Mercedes EQE 300 292 Sport Edi
Mileage	37150
First registration	20/08/2024
client availability date	31/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
136	Bumper Rear // Polish	Y
214	Door Front Right // Repair & Painting	N
271	Bumper Front / Trim Left / Replace	N
273	Bumper Front / Grid Left / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Bumper Rear // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Repair & Painting-scratch + dent



Bumper Front / Trim Left / Replace-cracked



Bumper Front / Grid Left / Replace-cracked