

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	306488
License plate	1YJG103
Vehicle identification number	W1K2470031J174081
Dossier	2020 045 104
Make	Mercedes B 180 d Bus.Sol
Mileage	148781
First registration	11/10/2020
client availability date	06/03/2026
inspectionDate	16/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
41	Windshield // Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
133	Bumper Rear // Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
340	Wheel Two Tone Front Right // Repair	Y
431	Seat Rear Left // Repair	Y
535	Trunk Compartment / Window Shelf / Replace	N
554	Central Console // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

## Damage Pictures







Damage within Renta-norm-



Windshield // Replace-scratch



Central Console // Replace Completely-scratch



Seat Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Painting-scratch






Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Trunk Compartment / Window Shelf / Replace-cracked