

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	313816
License plate	XY4795
Vehicle identification number	VR3USHNSSNJ662289
Dossier	2021342090
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	28180
First registration	30/06/2022
client availability date	27/05/2026
inspectionDate	29/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
54	Headlight / Front left / Replace	Y
41	Windshield // Replace	N
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	Y

## Damage Pictures




Bumper Rear // Smart Repair Medium-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Windshield // Replace-scratch



Headlight / Front left / Replace-scratch



Bumper Front // Painting-scratch