

INSPECTION REPORT


End of contract

GENERAL INFO

File	314917
License plate	2CRL347
Vehicle identification number	W1N9N0BB8PJ047183
Dossier	2021301060
Make	Mercedes EQA 250 AMG Line
Mileage	95025
First registration	28/10/2022
client availability date	10/06/2026
inspectionDate	16/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
132	Bumper Rear // Smart Repair Large	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
194	Door Rear Right // Repair & Painting	N
216	Door Front Right // Polish	N
654	Lettering Removal 15min	N
14	Bumper Front // Repair & Painting	N
66	Wing Front Left // Polish	Y
86	Door Front Left // Polish	Y
106	Door Rear Left // Polish	Y
150	Rear Bonnet // Smart Repair Small	N
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
883	Key Price Range 2 //	N

Damage Pictures




Bumper Front // Repair & Painting-scratch + dent



Key Price Range 2 // -missing




Rear Bonnet // Smart Repair Small-dent



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Polish-scratch



Wing Front Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Smart Repair Large-scratch



Lettering Removal 15min-Remainder stickers



Door Rear Right // Repair & Painting-scratch + dent



Door Front Right // Polish-scratch