

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	308629
License plate	2CXA216
Vehicle identification number	VNKKBAC310A270239
Dossier	2022185025
Make	Toyota Yaris 1.5 Hyb.Iconic e-
Mileage	60813
First registration	02/01/2023
client availability date	19/03/2026
inspectionDate	26/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
98	Rocker Panel Left / Cover Not Painted / Replace	Y
103	Door Rear Left // Painting	N
133	Bumper Rear // Painting	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	Y
208	Rocker Panel Right / Cover Not Painted / Replace	Y
210	Door Front Right // Smart Repair Small	N
282	Bumper Rear / Trim Center / Replace	N
860	Interior Cleaning // Small	N

## Damage Pictures



Damage within Renta-norm-scratch



Bumper Rear // Painting-scratch



Rocker Panel Left / Cover Not Painted / Replace-scratch




Bumper Front // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch





Door Front Right // Smart Repair Small-dent




Door Rear Right // Smart Repair Small-dent





Door Rear Left // Painting-scratch + dent



Interior Cleaning // Small-dirty



Rocker Panel Right / Cover Not Painted / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch