

INSPECTION REPORT


End of contract


GENERAL INFO

File	316268
License plate	2BKJ738
Vehicle identification number	VSSZZZKJZNR051875
Dossier	2021 349 055
Make	Seat Arona 1.0 81kW Move DSG
Mileage	45149
First registration	20/12/2021
client availability date	25/06/2026
inspectionDate	24/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
67	Wing Front Left / Trim / Replace	Y
271	Bumper Front / Trim Left / Replace	Y
237	Wing Front right / Trim / Replace	Y
272	Bumper Front / Trim Right / Replace	Y
18	Bumper Front / Spoiler / Replace	Y
64	Wing Front Left // Repair & Painting	Y
72	Side View Mirror Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
214	Door Front Right // Repair & Painting	Y
341	Wheel Alloy Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures




Bumper Front / Spoiler / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Door Rear Left // Smart Repair Small-scratch




Bumper Rear // Painting-scratch








Bumper Rear / Lower Cover Not Painted / Replace-scratch




Door Front Right // Repair & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain





Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front / Trim Right / Replace-scratch