

INSPECTION REPORT


End of contract

GENERAL INFO

File	320509
License plate	2EBR332
Vehicle identification number	W1N9M0BB0PN044645
Dossier	2022271009
Make	Mercedes EQB 250 Luxury Line A
Mileage	170412
First registration	21/08/2023
client availability date	19/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	Y
157	Rear Bonnet / Trim / Replace	Y
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
44	Windshield / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	Y
340	Wheel Two Tone Front Right // Repair	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Left // Polish-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Dashboard / Steering Wheel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-dent






Wing Rear Right // Repair & Painting-scratch + dent



Front Bonnet // Painting-Chemical reaction



Windshield / Trim / Replace-tear



Wing Rear Left // Painting-scratch



Rear Bonnet / Trim / Replace-scratch