

INSPECTION REPORT

End of contract

GENERAL INFO

File	307764
License plate	2AFK058
Vehicle identification number	VXKUPMHDM4021689
Dossier	2021 060 048
Make	Opel Corsa 1.2 75 Edition 5d/p
Mileage	6784
First registration	17/03/2021
client availability date	23/03/2026
inspectionDate	24/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N

Damage Pictures



Damage within Renta-norm-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-cracked