

INSPECTION REPORT

End of contract

GENERAL INFO

File	307601
License plate	2ABW483
Vehicle identification number	VR3UDYHSLJ970364
Dossier	2020 267 115
Make	Peugeot 2008 1.5BlueHDi 81kW A
Mileage	150749
First registration	12/02/2021
client availability date	10/03/2026
inspectionDate	20/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES


Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
63	Wing Front Left // Painting	Y
103	Door Rear Left // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	Y
544	Interior / Floor Covering / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures





Damage within Renta-norm-



Door Rear Left // Painting-scratch



Wing Front Left // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent




Door Front Right // Repair & Painting-scratch + dent





Bumper Front // Repair & Painting-scratch + dent



Interior / Floor Covering / Replace-tear